

**MSDS - Material Safety Data Sheet****Product Name: TRAP-FREE**

MSDS No.: 410

**I. Basic Information:**

Manufacturer: U.N.X. INCORPORATED

Address: 707 ARLINGTON BLVD.

City, ST Zip: GREENVILLE, NC 27858

Emergency Contact: CHEMTEL

Emergency Telephone Number: 800-255-3924

Contact: AMENDT; WILSON

Information Telephone Number: 252-756-8616

Last Update: 04/17/2006

Expiration Date:

Chemical State:  Liquid  Gas  SolidChemical Type:  Pure  Mixture

0	Health
0	Flammability
0	Reactivity
C	Pers. Protection

**II. Ingredients:** Trade Secret (N/D = Not Disclosed)

CAS No.	Chemical Name	% Range	EHS		IARC		SARA		OSHA PEL	ACGIH TLV	Other Limits
			NTP		SUB	Z	313				
TradeSecret	PSRN57948000-5070P	5-15									
7732185	Water	85-95									

**III. Hazardous Identification:**

Hazard Category:

 Acute  Chronic  Fire  Pressure  Reactive

Hazardous Identification Information:

**IV. First Aid Measures:**

Route(s) of Entry:

SKIN, EYES, INHALATION

Health Hazards (Acute and Chronic):

INHALATION, CAN IRRITATE NOSE, THROAT, AND LUNGS.

SKIN CONTACT, CAN IRRITATE OR CHAP SKIN.

INGESTION, WILL CAUSE GASTRIC DISTRESS, VOMITING AND DIARRHEA.

Signs and Symptoms:

PRODUCT CAN IRRITATE SKIN. EYE CONTACT CAN CAUSE BURNING AND EXTREME IRRITATION.

Medical Conditions Generally Aggravated by Exposure:

Emergency and First Aid Procedures:

# *MSDS - Material Safety Data Sheet*

**Product Name: TRAP-FREE**

**MSDS No.: 410**

FOR SKIN, FLUSH THOROUGHLY WITH SOAP AND WATER.

FOR EYES, FLUSH WITH WARM WATER FOR AT LEAST 15 MINUTES. CONTACT PHYSICIAN.

IF INGESTED, DRINK LARGE VOLUMES OF WATER FOLLOWED BY MILK THEN INDUCE VOMITING. CALL PHYSICIAN.

**Other Health Warnings:**

## ***V. Fire Fighting Measures:***

**Flash Point:** NO DATA

**Lower Explosive Limit:** NO DATA

**Upper Explosive Limit:** NO DATA

**F.P. Method:** NO DATA

**Fire Extinguishing Media:** NON-FLAMMABLE/NON-COMBUSTIBLE

**Special Fire Fighting Procedures:**

USE NIOSH/MSHA APPROVED SELF CONTAINED BREATHING APPARATUS WHERE PRODUCT IS INVOLVED IN FIRE.

**Unusual Fire and Explosion:**

AVOID CONTACT WITH ALUMINUM, ZINC, MAGNESIUM, COPPER. EXPLOSIVE HYDROGEN GAS CAN BE RELEASED.

## ***VI. Accidental Release Measures:***

**Steps to be Taken in Case Material is Released or Spilled:**

FOR A SMALL SPILL, IMMEDIATELY HOSE DOWN WITH COOL WATER AND DISPOSE DOWN DRAIN.  
FOR LARGE SPILLS, DIKE, COLLECT AND ADD SLOWLY TO A LARGE VOLUME OF COOL WATER WITH CONSTANT STIRRING. THEN SLOWLY NEUTRALIZE TO A pH OF 7.0 WITH MURATIC OR PHOSPHORIC ACID SOLUTIONS. DISPOSE OF DOWN DRAIN AFTER APPROVAL OF APPROPRIATE AUTHORITIES. CLEAN AND NEUTRALIZE ALL AREAS OF CONTACT.

## ***VII. Handling and Storage:***

**Precautions to be Taken:**

STORE IN A DRY PLACE. DO NOT STORE WITH STRONG ACIDS. KEEP CONTAINER CLOSED. DO NOT STORE IN DIRECT SUNLIGHT.

**Other Precautions:**

AVOID MIXING WITH OTHER CHEMICALS.

## ***VIII. Exposure Controls/Personal Protection:***

**Ventilation Requirements:**

AVOID BREATHING MIST. IF EXPOSURE IS LIKELY, USE FILTER OR PROTECTIVE RESPIRATOR. MECHANICAL VENTILATION IS ACCEPTABLE.

**Personal Protective Equipment:**

RUBBER GLOVES SHOULD BE WORN.

SAFETY GOGGLES SHOULD BE WORN.

OTHER PROTECTIVE MEASURES: HAVE AN EYE BATH AND SAFETY SHOWER CLOSE BY. IF POTENTIAL FOR SKIN CONTACT, HAVE AN ACID HAND WASH NEAR BY (ie. VINEGAR SOLUTION.).

WORK HYGIENIC PRACTICES: WASH HANDS, CHANGE OUT OF CLOTHES AS SOON AS POSSIBLE. WASH CLOTHES. SHOWER OR BATHE AS SOON AS POSSIBLE.

# MSDS - Material Safety Data Sheet

**Product Name: TRAP-FREE**

MSDS No.: 410

## IX. Physical and Chemical Properties:

Boiling Point: 99°C

Melting Point: NO DATA

Evaporation Rate (Butyl Acetate = 1): NO DATA

Vapor Pressure (mm Hg.): NO DATA

Specific Gravity (H2O = 1): 0.99600

Vapor Density (AIR = 1): NO DATA

Solubility In Water: EXCELLENT

Appearance and Odor: GREEN LIQUID, ENZYME AND FERMENTATED  
ODOR

Other Information: THIS PRODUCT CONTAINS NO PHOSPHATES  
DRAIN CLEANER

## X. Stability and Reactivity:

Stability:

VERY STABLE

Incompatibility (Materials to Avoid):

AVOID CONTACT WITH ACIDS AND OTHER LAUNDRY CHEMICALS. STRONG DECOMPOSITION REACTION CAN RESULT.

Decomposition/By Products:

AVOID CONTACT WITH ALUMINUM, ZINC, MAGNESIUM, COPPER. EXPLOSIVE HYDROGEN GAS CAN BE RELEASED.

Hazardous Polymerization:

HAZARDOUS POLYMERIZATION WILL NOT OCCUR.

## XI. Toxicological Information:

CONTACT U.N.X. INCORPORATED

## XII. Ecological Information:

CONTACT U.N.X. INCORPORATED

## XIII. Disposal Considerations:

FOR A SMALL SPILL, IMMEDIATELY HOSE DOWN WITH COOL WATER AND DISPOSE DOWN DRAIN.  
FOR LARGE SPILLS, DIKE, COLLECT AND ADD SLOWLY TO A LARGE VOLUME OF COOL WATER WITH CONSTANT STIRRING. THEN SLOWLY NEUTRALIZE TO A pH OF 7.0 WITH MURATIC OR PHOSPHORIC ACID SOLUTIONS. DISPOSE OF DOWN DRAIN AFTER APPROVAL OF APPROPRIATE AUTHORITIES. CLEAN AND NEUTRALIZE ALL AREAS OF CONTACT.

## XIV. Transport Information:

NOT DOT REGULATED

## XV. Regulatory Information:

UNLESS OTHERWISE NOTED, NO COMPONENTS ARE SARA TITLE 3 SECTION 313 40 CFR LISTED MATERIALS.  
THE INGREDIENTS OF THIS PRODUCT ARE LISTED ON THE TSCA INVENTORY.  
THIS PRODUCT IS NOT MADE WITH VOC'S THAT COULD CAUSE DAMAGE TO THE OZONE LAYER.

## XVI. Other Information:

***MSDS - Material Safety Data Sheet***

***Product Name: TRAP-FREE***

***MSDS No.: 410***